





SPINDELN/GEWINDESTANGEN



Mechanische Spindeln und Gewindestangen Mechanical spindles and tie rods



No.	 mm	A mm	B mm		
-----	--	------	------	---	---

Spindeln Spindles M8

G140	8	85	10	10	0,03
------	---	----	----	----	------

Spindeln Spindles M10

G141-3	10	105	15	12	0,06
G60-1	10	150	15	12	0,1

Spindeln Spindles M12

G 60-2	12	190	20	14	0,2
--------	----	-----	----	----	-----

Spindeln Spindles M14x1,5

G167-1	14	60	21	17	0,1
G100-HS	14	100	21	17	0,2
G100-1	14	130	21	17	0,2
G60-3	14	200	21	17	● 0,3
GS100-1S	14	250	35	17	0,55

Spindeln Spindles M16x1,5

G167-2	16	70	20	17	● 0,1
G169-1	16	70	20	17	● 0,1
G169-2	16	90	20	17	● 0,2

Spindeln Spindles M18x1,5

G167-3	18	70	20	19	● 0,2
G118-1	18	130	20	19	● 0,3
G132	18	240	22	19	● 0,5

Spindeln Spindles G 1/2"x14

G167-4	21	110	23	22	● 0,3
G100-2	21	210	23	22	● 0,6
G60-5	21	230	23	22	0,6
G135-3	21	270	23	22	● 0,8

Spindeln Spindles G3/4"x14

G150	26	180	35	27	● 1,0
G100-3	26	280	35	27	● 1,3
G100-3L	26	360	35	27	● 1,7

Spindeln Spindles G1"x11

G100-5	33	310	45	36	● 2,2
G100-5L	33	455	45	32	● 2,6
G160	33	370	45	36	● 2,3

Gewindestangen Tie Rods

G172-1	12	200	M12	0,2
G172-2	16	280	M16	0,5
G172-3	20	370	M20	1,0